Oil Field Environmental Incident Summary

Responsible Party: Black Hills Trucking **Well Operator:** OXY USA INC. **Well Name:** LEISS 2-23-26H-143-96

Field Name: FAYETTE Well File #: 22893

Date Incident:9/5/2014Time Incident:09:30Facility ID Number:County:DUNNTwp:143Rng:96Sec:14Qtr:

Location Description:

Submitted By: Robyn Espinoza Received By:

Contact Person: Robyn Espinoza

125 Gta Dr

Dickinson, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident Truck Overflow

Release Contained in Dike Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil 2 Barrels 1 Barrels 1 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/9/2014 Clean Up Concluded: 9/5/2014

Risk Evaluation:

None

Areal Extent:

Spill was contained on the well pad

Potential Environmental Impacts:

Contaminated surface material on well pad.

Action Taken or Planned:

Black Hills recovered 1 bbl with absorbent pads and SM Fencing was dispatched immediately to remove all contaminated material.

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 9/5/2014 Status: Reviewed; O&G Lead Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to truck overflow remained on location, according to the report. NDIC retains oversight.